

No. PB-1/ 251 / of 2020
Office of The Deputy Executive Engineer,
Vapi (R & B) Sub Division,
Phone No. (0260) – 2401129
Vapi. Dtd. 11/02/2020

To
The Principal,
Samarpan Gnyan School ,
At- Post – Rata,
Vapi - 396191
Gujarat.


Subject :- Issue Building Stability Certificate.

Ref. :- Your office Letter No. SGS/793/VAPI/2020, Dtd. – 04.02.2020.

With reference to above cited subject, It is to inform you that by vide reference letter "Building Stability Certificate" is asked for M/s. Samarpan Gnyan School, At- Post – Rata, Vapi for Educational purpose.

The School Building (Ground + 2) was inspected by me on date 06.02.2020 and was certified by consultants. With reference to the certificate for the Stability of building given by Harish & Associates, Consulting Engineers, Designer & Planner is found ok. This is for your kind information.

D.A. – Certificate


Deputy Executive Engineer
Vapi (R & B) Sub Division
Vapi

Copy submitted to Executive Engineer, Valsad (R & B) Division, Valsad for kindly information.


MANAGER
SAMARPAN GNYAN SCHOOL
RATA, VAPI.


Principal
SAMARPAN GNYAN SCHOOL
RATA, VAPI.

Certificate

This is to certify that the School Building (Ground + 2) was inspected by me on date 06.02.2020 and the certificate given by Harish & Associates, Consulting Engineers, Designer & Planner for Samarpan Gnyan School building is found in order.

Place :- Vapi

Date :- 06 /02 /2020



Deputy Executive Engineer
Vapi (R&B) Sub Division
Vapi



MANAGER
SAMARPAN GNYAN SCHOOL
RATA, VAPI.



Principal
SAMARPAN GNYAN SCHOOL
RATA, VAPI.